

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments |
|---|------|-----|------|--|---|----------------------|----------|
| 1 | BRS | L1 | 4 | ("5356849" or "5444031" or "5464605" or "5674472").pn. and metal | USPA T | 2003/02/0 3 16:02 | |
| 2 | BRS | L2 | 588 | impregnat\$5 near25 carbon\$5 near25 activ\$6 near25 metal | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB | 2003/02/0 3 13:27 | |
| 3 | BRS | L9 | 12 | impregnat\$5 near25 (activ\$5 near5 carbon\$5) near25 (heavy adj metal) | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB | 2003/02/0 3 13:59 | |
| 4 | IS&R | L16 | 1 | ("4578256").PN. | USPA T | 2003/02/0 3 14:02 | |
| 5 | BRS | L17 | 1123 | (charcoal or coal or carbon) near25 activat\$4 near50 (pyrite or di\$1sulfide or cyanochromate or sulfide or hexa\$1cyanomanganate) | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB | 2003/02/0 3 14:06 | |
| 6 | BRS | L24 | 773 | (charcoal or coal or carbon) near10 activat\$4 near10 (pyrite or di\$1sulfide or cyanochromate or sulfide or hexa\$1cyanomanganate) | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB | 2003/02/0 3 14:09 | |

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments |
|----|------|-----|------|--|--|------------------|----------|
| 7 | BRS | L31 | 12 | (charcoal or coal or carbon) near10 activat\$4 near10 (pyrite or cyanochromate or hexa\$1cyanomanganate) | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM-TDB | 2003/02/03 14:16 | |
| 8 | BRS | L38 | 810 | (activat\$3 near10 carbon near10 (method or process)).clm. and (metal).clm. | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM-TDB | 2003/02/03 14:36 | |
| 9 | BRS | L45 | 23 | (cigarette or cigar or tobacco) near350 (activ\$6 near25 carbon near50 impregnat\$5) | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM-TDB | 2003/02/03 14:43 | |
| 10 | BRS | L52 | 33 | (cigarette or cigar or tobacco) near350 (activ\$6 near25 (coal or charcoal or carbon) near50 impregnat\$5) | USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM-TDB | 2003/02/03 15:08 | |

| | Type | L # | Hits | Search Text | DBs | Time Stamp | Comments |
|----|------|-----|------|---|--|----------------------|----------|
| 11 | BRS | L59 | 12 | 131/.cccls. and (chemi\$sorption or (chemical adj adsorption)) | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM _ TDB | 2003/02/0 3 15:29 | |
| 12 | BRS | L66 | 114 | 131/.cccls. and carbon near25 activ\$ | USOC R | 2003/02/0 3 15:30 | |
| 13 | BRS | L67 | 22 | 131/.cccls. and carbon near25 (activate or activation or activated) near50 (metal or copper or iron) | USOC R | 2003/02/0 3 15:34 | |
| 14 | BRS | L68 | 0 | ((iron adj carbon adj nitrogen) or iron\$1carbon\$1nitroge n\$) near50 charcoal | USOC R | 2003/02/0 3 15:37 | |
| 15 | BRS | L69 | 0 | ((iron adj carbon adj nitrogen) or iron\$1carbon\$1nitroge n\$) near50 charcoal | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM _ TDB | 2003/02/0 3 15:38 | |
| 16 | BRS | L76 | 0 | (sulfur or nitrogen) near5 ligation near50 ((charcoal or carbon) near10 activ\$6) | USPA T | 2003/02/0 3 16:03 | |
| 17 | BRS | L77 | 2 | (sulfur or nitrogen) near5 ligation | USPA T | 2003/02/0 3 16:06 | |
| 18 | BRS | L78 | 33 | ((sulfur or nitrogen or metal) near5 (ligand or ligate or ligated or ligation)) near50 (coal or charcoal or (activat\$ near2 carbon)) | USPA T; US-P GPUB ; EPO; JPO; DERW ENT; IBM _ TDB | 2003/02/0 3 16:10 | |